

August 9, 1989
R-6570-YYB-2305


To:	M. Babich	62-15
	D. Babst	93-54
	H. Bauer	91-10
	C. Cherberg	62-15
	T. Frees	93-03
	L. Hedin	93-03
	J. Johnston	99-05
	C. Kalkstine	99-05
	T. Macnamara	62-15
	J. Stephenson	62-15

Subject: Incident Report at the 4-01 Building,
August 1, 1989

At approximately 1:00 p.m. on August 1, 1989, roughly one gallon of sulfuric acid was spilled at the Wastewater Treatment Facility. This spill was caused by the breaking of the glass sight gauge on a pressurized sulfuric line.

Since only a small amount of sulfuric acid was spilled, the City of Renton was not notified. The Boeing Fire Department, in Level "B" protection, entered the area and neutralized the spill.

Once Boeing firemen had neutralized the spill, two hazmat members entered the area. The hazmat members re-checked the pH. Once the pH reached a satisfactory reading, hazmat members proceeded to clean and dispose of the neutralized solution. At approximately 2:40 p.m. the incident was terminated.


Yvette Barnett
Orgn. R-6570, M/S 62-15
Phone: 237-9263

YYB:LKS

Enclosures: Boeing Fire Department Report